

The “Stump the Chump” Instrument Rating Workbook



ERRATA AND UPDATES

Revision 2.

Corrections and updates to the First Edition of the Book.

Daniele Paolo Scarpazza

Errata Revision 2.
Published on February 16th, 2026.

Applies to the book's first edition, published on January 15th, 2026,
ISBN: 9798278232162.
© 2026, Daniele Paolo Scarpazza. All rights reserved.

Published by Independent Aviation Consultants,
an Illinois Limited Liability Company.
Find this book's errata at the publisher's website,
<http://independentaviation.training>.

The book is available on mypilotstore.com, Amazon, and gumroad.com.

Any copyrighted text and graphics quoted or reproduced in this publication are used under the Fair Use doctrine for commentary, teaching and educational purposes. No infringement is intended. All rights belong to the respective copyright holders.

Typeset by the author using L^AT_EX.

Errata

These Errata apply identically to the print and to the digital edition of the book.

1 Question 6

On page 23 (page 29, according to the PDF numbering), the third paragraph reads:

“You cleared route is via GPS airway T257 to COPLS waypoint”

It should read:

“**Your** cleared route is via GPS airway T257 to COPLS waypoint”.

2 Question 11

In sentence: “The sources of that determination are 14 CFR § 1.1, the ACS documents, the IFH and the CUG, as discussed at length in the answer to Question 48,” abbreviation “CUG” is not defined in the Abbreviations chapter at the end of the book.

By CUG we mean the Aeronautical Chart Users’ Guide, currently offered by the FAA at address https://aeronav.faa.gov/user_guide/cug-complete_20250612.pdf.

3 Question 23

On page 84 (page 90, according to the PDF numbering), fragment:

“which allows the use of GPS to naviate the final approach segment of a VOR approach”

should read:

“which allows the use of GPS to **navigate** the final approach segment of a VOR approach”.

4 Question 24

On page 85 (page 91, according to the PDF numbering), list item:

“the ILS or LOC Runway 11 approach at Portland, Maine (Figure 36, on page 114)”

should read:

“the ILS or LOC Runway 11 approach at **Portland**, Maine (Figure 36, on page 114)”

5 Question 30

On page 103 (page 109, according to the PDF numbering), in the third list item, the quote

“at a normal rate of descent using normal maneuvers”

should read

“at a normal rate of descent using normal **maneuvers**”.

6 Question 35

On page 111 (page 117, according to the PDF numbering), the sentence

“The is typically the case in seaplane bases, where there’s simply no runway.”

should read

“**This** is typically the case in seaplane bases, where there’s simply no runway.”

7 Abbreviations

On page 250 (page 256, according to the PDF numbering), in the definition of the VOR abbreviation, the expression:

“(this is something that NBDs and ADFs can do)”

Should read:

“(this is something that **NDBs** and ADFs can do)”

Updates

No updates at this time.

Disclaimers

No generative artificial intelligence (AI) was used in the writing of this work. The author expressly prohibits any entity from using this publication for the purpose of training AI technologies, including without limitation technologies that are capable of generating works in the same style or genre as this publication. The author reserves all rights to license uses of this work for AI training.